




SERIAL #



ROUTINE SKIN PLATE REPAIRS

3/16" FULL THICKNESS/CONTINUOUS



NOTES:
*) CALL MANUFACTURER FOR SIZES GREATER THAN 18" x 18".

EFFICIENCY PRODUCTION INC.	
685 HULL RD. MASON MI. 48854 Ph. (517)-676-8800 . FAX (517) 676-0373	
DATE	12-14-12
DWG. #	XLP-REPAIR
DRAWN BY	J REMACLE
PSF = SEE CHART	
S.O.#	N/A
PAGE:	
EFFICIENCY STOCK	XLP REPAIR DRAWINGS
	STANDARD REPAIRS